

Memo

Project: National Paediatric Hospital

Report Type: Summary of Noise Vibration & Movement Monitoring Results

Period of Monitoring: 31st May 2021 – 5th July 2021

Introduction

Contained within the project documents for the National Children's Hospital development are requirements for Environmental Monitoring to be completed during construction works. This monitoring regime includes recording noise at the perimeter of the site and ground vibration at the perimeter of the site. Permissible limits for each monitoring regime have been set out in the Project EIS which was submitted with the Planning Permission for the Hospital.

The number of Monitoring points will vary throughout the project depending on the construction works being undertaken. Additional monitoring points may be added if features of adjacent properties require it.

Works on site during this monitoring period include, but are not limited to:

O'Reilly Avenue/ Energy centre –Loading Bay, Deliveries, Waste skip removal and removal of excavation materials. FM Tunnel works. Façade works.

Hospital – Construction of upper levels and interior works, breaking of temporary wall and construction traffic, waste removal and façade works.

Cameron Square – No works listed in the Environmental Monitoring Report.

South Circular Road – Interior works, HGV Loading bay, Façade stone works and Scaffolding loading

Mount Brown – Waste removal, concrete deliveries and ground works.

Brookfield Clinic – No works listed in the Environmental Monitoring Report.

Energy Centre – Steel fixing, waste removal, rebar and steel fixing, ground works. Movement of materials, area clean up and façade works.

Vibration Monitoring.

Vibration monitors have been located at the 'closest part of sensitive property' as per the Project Environmental Impact Statement where feasible or alternatively at the site hoarding. The monitors will be located as per the above adjacent to locations where significant works are ongoing on site.

The Project Environmental Impact Statement (EIS) that was part of the project Planning Permission established vibration limit at structures depending on their condition and type. Please see tables below for the limits set.

Memo

Table 11.7: Allowable vibration during construction phase for soundly constructed buildings

Allowable vibration (in terms of peak particle velocity) at the closest part of sensitive property to the source of vibration, at a frequency of		
Less than 10Hz	10 to 50Hz	50 to 100Hz (and above)
15 mm/s	20 mm/s	50 mm/s

Table 11.8: Allowable vibration during construction phase for sensitive buildings

Allowable vibration (in terms of peak particle velocity) at the closest part of sensitive property to the source of vibration, at a frequency of		
Less than 10Hz	10 to 50Hz	50 to 100Hz (and above)
3 mm/s	3 – 8 mm/s	8 – 10 mm/s

Site operations are monitored using a traffic light trigger system of Green, Amber and Red trigger levels with the Red trigger level set at a vibration limit of 3mm/s PPV which corresponds to the lowest permissible vibration limit for sensitive structures. Any vibration level recorded below Red levels is acceptable within the limits established in Planning.

Number of Monitors on Site:

During the monitoring period summarised for this report there were up to 16 active vibration monitors installed at the perimeter of the site.

Location of Vibration and Noise Monitors:

The layout of the monitors is as seen below:



Location of Noise and Vibration Monitors

Memo

There are concentrations of monitors at the boundaries with Cameron Square and O'Reilly Avenue where works have been ongoing on site in proximity to neighbouring properties.



Location of Noise and Vibration Monitors near O'Reilly Avenue

Observations:

Executive Summary:

Vibration monitors have been placed at the 'closest part of the sensitive properties' as per the EIS where this is feasible. Most vibration readings during the monitoring period recorded readings below the limit specified within the Project EIS. Vibration monitors V1, V13, V18, V19, V20, A1 & A2 have been excluded from this report as they are not relevant to the conditions for the residents adjacent to the site. From the remaining 11 monitors:

- 3 monitor recorded readings above the limit specified within the Project EIS.
- No monitors were offline during the timeframe covered in this report.

Detailed Summary:

Sensor (V2 – 3666) (James' Walk)

- All vibration readings recorded vibrations below the limit specified within the Project EIS.

Memo

Sensor (V3 – 8995) (South Circular Road)

- All vibration readings recorded vibrations below the limit specified within the Project EIS.

Sensor (V5 – 5037) (Cameron Square)

- All vibration readings recorded vibrations below the limit specified within the Project EIS.

Sensor (V6 - 5044) (Cameron Square)

- All vibration readings recorded vibrations below the limit specified within the Project EIS.

Sensor (V7 - 5017) (Old Kilmainham Road)

- Vibration readings recorded vibrations above the limit specified within the Project EIS on the following days:
 - 15.06.2021. Cause: "This breach was caused by a knock to the monitor from the homeowner. There was no construction activity in the area at this time [approximately 4PM]". Mitigation: None.
 - 02.07.2021. Cause: "This breach was caused by an accidental knock to the monitor from the homeowner.". Mitigation: None.

Sensor (V8 - 5035) (Brookfield Clinic)

- All vibration readings recorded vibrations below the limit specified within the Project EIS.

Sensor (V9 – 5056) (O'Reilly Avenue)

- Vibration readings recorded vibrations above the limit specified within the Project EIS on the following days:
 - 15.06.2021. Cause: "These breaches were caused by renovation work to the house and garden of the home directly beside the monitor location". Mitigation: None.
 - 16.06.2021. Cause: "These breaches were caused by renovation work to the house and garden of the home directly beside the monitor location". Mitigation: None.
 - 17.06.2021. Cause: None given. Mitigation: None given.

Sensor (V10 – 4183) (O'Reilly Avenue)

- All vibration readings recorded vibrations below the limit specified within the Project EIS.

Sensor (V11 – 8988) (O'Reilly Avenue)

- All vibration readings recorded vibrations below the limit specified within the Project EIS.

Sensor (V12 – 5043) (O'Reilly Avenue)

- Vibration readings recorded vibrations above the limit specified within the Project EIS on the following days:
 - 05.07.2021. Cause: None given. Mitigation: None given.

Sensor (V14 - 3835) (South Circular Road)

- All vibration readings recorded vibrations below the limit specified within the Project EIS.

Memo

Noise Monitoring.

During the report period noise monitors have been placed at the ‘closest part of sensitive property’ as per the Project EIS where this has been feasible, or alternatively to the outside face of the site hoarding. When works are ongoing the noise monitor sensors run continuously, and readings are recorded in decibels (dB) LA_{eq1hr} . Decibels is the standard unit of measurement of sound energy and ‘ LA_{eq1hr} ’ means that sensors record all levels of sound over a 1-hour period and then calculate an average equivalent decibel level as if the sound was continuous. Isolated instantaneous loud noises are thus averaged out.

The Project Environmental Impact Statement (EIS) that was part of the project Planning Permission established a noise limit at residential dwellings of 70dB LA_{eq1hr} . Site operations are monitored using a traffic light trigger system of Green, Amber and Red trigger levels with the Red trigger level set at the noise limit set out in the project EIS (70 dB LA_{eq1hr}). Any noise level recorded below Red levels is acceptable within the limits established in Planning.

Number of Noise Monitors on Site:

During the monitoring period summarised for this report there were up to 20 active monitors at the site boundaries.

Observations:

Executive Summary:

Noise monitors 07, 08, 15, 16, 17, 18, 19 & 20 have been excluded from this report as they are not relevant to the conditions for the residents adjacent to the site. From the remaining 12 monitors:

- 10 number monitors recorded readings above the limit specified within the Project EIS.
- 1 number monitors were offline for at least 1 day during the timeframe covered by this report.

Detailed Summary:

The monitoring results for noise for this period were within the limits set out in the Project EIS with the following exceptions:

Monitor 01 (Cameron Square)

- Noise levels above the limit specified within the Project EIS were recorded on the following dates: 9th June 2021. The noise report does not note any explanation nor mitigation.
- All noise readings recorded noise levels below the limit specified within the DCC 10-hour limit.

Monitor 02 (O’Reilly Avenue)

- Noise levels above the limit specified within the Project EIS were recorded on the following dates:
 - 13th June 2021. The noise report stated “There was no construction activity on this date. [Sunday]”.
 - 18th June 2021. The noise report stated, “Breach was the result of the grass in the rear walkway being cut by multiple trimmers”. No mitigation was noted.
- All noise readings recorded noise levels below the limit specified within the DCC 10-hour limit.

Memo

Monitor 03 (Mace)

- Noise levels above the limit specified within the Project EIS were recorded on the following dates: 31st May, 1st, 2nd, 3rd, 4th, 5th, 6th, 7th, 8th, 9th, 10th, 11th, 14th, 15th, 16th, 17th, 18th, 19th, 20th, 21st, 22nd, 23rd, 24th, 25th, 26th, 27th, 28th, 29th and 30th June and 1st, 2nd, 3rd and 4th July 2021. The noise report stated “this noise monitor is located close to the busy SC road. this monitor is constantly exceeding, inclusive of outside of construction hours. These exceedances are due to ambient traffic” Exceedances were noted on weekends when there was no construction reported on site.
- All noise readings recorded noise levels below the limit specified within the DCC 10-hour limit.

Monitor 04 (Mount Brown Road)

- Noise levels above the limit specified within the Project EIS were recorded on the following dates: 31st May, 1st, 2nd, 3rd, 4th, 5th, 6th, 8th, 9th, 10th, 11th, 12th, 13th, 14th, 15th, 16th, 17th, 18th, 19th, 21st, 22nd, 23rd, 24th, 25th, 26th, 27th, 28th, 29th and 30th June and 1st, 2nd, 3rd and 4th July 2021. The noise report stated “This noise monitor is located on the busy R810 road. The monitor is constantly in breach due to its close proximity to the road. We often see high breaches outside of construction hours therefore these breaches are deemed to be due to ambient traffic noise.” Exceedances were noted on weekends when there was no construction reported on site.
- All noise readings recorded noise levels below the limit specified within the DCC 10-hour limit.

Monitor 05 (O’Reilly Avenue)

- Noise levels above the limit specified within the Project EIS were recorded on the following dates: 18th June 2021. The noise report stated “Breach was the result of the grass in the rear walkway being cut by multiple trimmers”. No mitigation was noted.
- All noise readings recorded noise levels below the limit specified within the DCC 10-hour limit.

Monitor 06 (O’Reilly Avenue)

- Noise levels above the limit specified within the Project EIS were recorded on the following dates: 2nd June 2021. The noise report stated “There was no construction activity of a loud nature at this time in the area, [11:00am].” No mitigation is noted.
- All noise readings recorded noise levels below the limit specified within the DCC 10-hour limit.

Monitor 09 (James’ Walk)

- All noise readings recorded noise levels below the limit specified within the Project EIS.
- The monitor was off for on a continuous basis from the 12th – 17th June 2021. The noise report does not provide a cause.
- All noise readings recorded noise levels below the limit specified within the DCC 10-hour limit.

Memo

Monitor 10 (Brookfield Clinic)

- Noise levels above the limit specified within the Project EIS were recorded on the following dates: 29th June 2021. The noise report stated “There was no construction activity in the area at this time, [11:00am].” No mitigation is noted.
- All noise readings recorded noise levels below the limit specified within the DCC 10-hour limit.

Monitor 11 (Cameron Square)

- Noise levels above the limit specified within the Project EIS were recorded on: 31st May 2021. The noise report does not note any explanation nor mitigation
- All noise readings recorded noise levels below the limit specified within the DCC 10-hour limit.

Monitor 12 (Cameron Square)

- All noise readings recorded noise levels below the limit specified within the Project EIS.
- All noise readings recorded noise levels below the limit specified within the DCC 10-hour limit.

Monitor 13 (64 O’Reilly Avenue)

- Noise levels above the limit specified within the Project EIS were recorded on the following dates: 18th June 2021. The noise report stated “Breach was the result of the grass in the rear walkway being cut by multiple trimmers”. No mitigation was noted.
- All noise readings recorded noise levels below the limit specified within the DCC 10-hour limit.

Monitor 14 (South Circular Road)

- Noise levels above the limit specified within the Project EIS were recorded on the following dates: 31st May 2021, 1st, 2nd, 3rd, 4th, 5th, 6th, 7th, 8th, 9th, 10th, 11th, 12th, 13th, 14th, 15th, 17th, 18th, 19th, 20th, 21st, 22nd, 23rd, 24th, 25th, 26th, 27th, 28th, 29th, and 30th June and 1st, 2nd, 3rd and 4th July 2021. The noise report stated “This noise monitor is located on the busy South Circular Road. The monitor is constantly in breach, inclusive of outside of construction hours therefore these breaches are deemed to be due to ambient traffic noise.” Exceedances were noted on weekends when there was no construction on site.
- All noise readings recorded noise levels below the limit specified within the DCC 10-hour limit.